

Metal Press

Equipment CheckList: Please ensure you have collected everything

Mill:

- 1. Black Milling machine base unit
- 2. Yellow Hopper
- 3. Electrical cable
- 4. RCD

Press:

- 5. Wood base unit
- 6. Metal Press
- 7. Stainless steel tray
- 8. Wooden pressing block
- 9. Stainless steel former
- 10.Six wooden racks
- 11. Five 'cheese' cloths
- 12. Turning handle & bolt

Accessories:

- 1. Four large flexible buckets
- 2. One sieving bucket
- 3. Measuring Jug (for use as a scoop)
- 4. One laminated Instructions / Equipment List card

Clean immediately after use (before pulp/juice has time to dry):

Mill:

- (1) Use a low pressure hose to run water down the inside of the hopper with the mill still running. This will discharge the bulk of the residual pulp.
- (2) Turn mill off and disconnect from the mains power supply
- (3) Remove hopper and wash all parts of the mill (excluding motor) with low pressure fresh water and nylon brush. NB Sharp blades.

Avoid letting water run into the small hole in the motor housing that gives access to the cut-off safety switch and do not spray water onto the switch and power socket.

<u>Press:</u> After use, wash all parts of the press with fresh water. The cloths are machine washable at 40C but drip dry, do not spin. The wooden racks should be scrubbed clean and allowed to dry before storage. Damp boards go mouldy.

Buckets etc: Wash all out with fresh water.

Metal Press Equipment List 27/07/11